

CUSTOMER NO. 30430


PATENT APPLICATION  
Docket No. 99-C-179D1

**REMARKS**

A post-Notice of Allowance review of this application revealed two errors in the specification and one error in the drawings. This Rule 312 Amendment is presented to address and correct those errors. With respect to the specification errors, it was noted that the logic levels of the signal had been inaccurately/oppositely described. Correction has been made above. With respect to the drawing error, it was noted that an incorrect voltage reference notation was used with respect to a ground connection in Figure 2B. Correction is as noted above and in the attached marked-up drawing sheet. A replacement sheet for Figure 2B with the correction is also included.

Respectfully submitted,

JENKENS & GILCHRIST,  
A Professional Corporation

By: 

Andre M. Szwalski  
Registration No. 35,701

1445 Ross Avenue, Suite 3700  
Dallas, Texas 75202-2799  
Tel: 214/855-4795  
Fax: 214/855-4300

CUSTOMER NO. 30430

PATENT APPLICATION  
Docket No. 99-C-179D1

**IN THE DRAWINGS:**

In the lower right-hand corner of Figure 2B, please change the ground reference from "VCCSUB" to "VSS" as indicated in red in the attached proposed drawing correction.



99-C-179

3/6




FIG. 2B